

Daily Field Report

Bolts in Epoxy
Bolts in New Concrete

Concrete Dowels

Fireproofing Job Address: 870 El Camino Del Mar Holdowns Masonry San Francisco, CA Post Tensioned Concrete Pull Test Permit(s): 2018.05.23.9894 2021.11.12.2309 Plans Dated: 02/16/22 Roof Nailing Date of Inspection: 03/23/22 Shear Walls Shotcrete Nick reported to Alfred Thompson Suskind with at jobsite. Torque Test Observed placement of: Set #4 Design Set #1 Set #2 Set #3 Concrete Shotcrete ✓ Rebar PSI ✓ Grade Beam Columns / Footing Agg. Size Post Footing Slump PT Deck ✓ Retaining Walls SOG Stairs Field Stem Wall Underpinning Wall # per set Other: at the following location(s): Mix# see GREEN shaded areas on the Reference PDF for locations @ level 1 foundation & floor framing plan (1/S2.01) as per 1/S5.02 Mix PSI Rebar appears to be in general compliance with approved plans Agg. Size → OK TO POUR PENDING CITY INSPECTION and EOR APPROVAL Monitored mix #, slump, temperature, and time limit. Prepared test Slump Cylinders Panels Other: Mix Temp Sampled from Truck Chute Nozzle Other: Air Temp Strength tested at 28 days. Supplier: Total Yds Location(s) sampled: Total Number Of Sets: 0 Total Number of Samples: Observed placement of | ✓ | Bolts in new concrete | | Epoxy Bolts | | Epoxy Dowels | | Other: For: In above locations: (2) HDU8/s (7/8" ø galvanized all thread w/ 2x nut & washer) // (1) HDU4/s (5/8" ø galvanized all thread w/ 2x nut & washer) // ABs (5/8" ø J bolts) @ 16" O.C. Epoxy Type: YES () NO (Exp. Date: Cleaned: Performed To the following specified tensions: on ✓ Work was observed was, to the best of Nick 's knowledge, in conformance with approved plans, specifications, and application standards of workmanship. If present, any exceptions or non-compliance conditions were brought to the attention of for corrective action, and are as follows: See attached non-compliance report. Contractor's acknowledgment of receipt: