

Daily Field Report

Bolts in Epoxy Bolts in New Concrete

Concrete

Dowels

Fireproofing Job Address: 870 El Camino Del Mar Holdowns Masonry San Francisco, CA Post Tensioned Concrete Pull Test Permit(s): 2018.05.23.9894 2021.11.12.2309 Rebar Roof Nailing Date of Inspection: 06/29/22 Shear Walls Shotcrete Gaetano Basso reported to Thompson Suskind Reed with at jobsite. Torque Test Observed placement of: Design Set #1 Set #2 Set #3 **Set #4** Concrete Shotcrete ✓ Rebar Other: PSI Footing Grade Beam Agg. Size Mat Slab Piles Post Footing Slump √ sog PT Deck Retaining Walls Stairs Field Stem Wall Underpinning Wall # per set Other: at the following location(s): Page S2.01 6.2-6.9 & A-D per 2/S5.02 Mix# Reinforcement appears to be in general compliance with the approved plans. Ok Mix PSI to pour above section(s) pending DBI & EOR approval and NOTED item below. Agg. Size Compliant (Monitored mix #, slump, temperature, and time limit. Prepared test Slump Cylinders | Panels | Other: Mix Temp Sampled from Truck Chute Nozzle Other: Air Temp Strength tested at 28 days. Supplier: Location(s) sampled: Total Yds Total Number Of Sets: 0 Total Number of Samples: 0 Observed placement of Bolts in new concrete Epoxy Bolts Epoxy Dowels Other: For: **Epoxy** Type: Exp. Date: Cleaned: YES () NO () Performed To the following specified tensions: As shown in 1/S5.02 and 12/S5.04 the edge of the slab requires a hooked edge bar in addition to the poured in Z bars. Will check prior to pour. ✓ Work was observed was, to the best of Gaetano Basso 's knowledge, in conformance with approved plans, specifications, and application standards of workmanship. If present, any exceptions or non-compliance conditions were brought to the attention of for corrective action, and are as follows:_____ See attached non-compliance report. Contractor's acknowledgment of receipt: