

## Daily Field Report

Job Address:

870 El Camino Del Mar

San Francisco, CA

Permit(s): 2018.05.23.9894 S1

Date of Inspection: 06/15/22

Brandon Burdine reported to GuerlImo with

Bolts in Epoxy
Bolts in New Concrete
Concrete
Dowels
Fireproofing
Holdowns
Masonry
Post Tensioned Concrete
Pull Test
Rebar
Roof Nailing
Shear Walls
Shotcrete

at jobsite. Torque Test

Observed placement of:	Design Set #1 Set #2 Set #3 Set #4
Concrete Shotcrete PRebar Other:	PSI
For: Columns Footing Grade Beam	
Mat Slab Piers Piles Post Footing	Agg. Size
PT Deck Retaining Walls SOG Stairs	Slump
Stem Wall Underpinning Wall	<u>Field</u>
Other: Pan Deck at the following location(s):	# per set
Page S2.01 - (6.25-4, A-G) per 2/S5.02 and 10/S7.01	Mix#
OK TO POUR PENDING CITY INSPECTION	Mix PSI
	Agg. Size
Maritanadaria # abassa bassa b	Compliant Y N Y N Y N Y N
Monitored mix #, slump, temperature, and time limit. Prepared test	Slump
Cylinders Panels Other:  Sampled from Truck Chute Nozzle Other:	Mix Temp
Sampled fromTruck ChuteNozzleOther:Strength tested at 28 days. Supplier:	Air Temp
Location(s) sampled:	Total Yds
Total Number Of Sets: 0 Total Number of Samples: 0	Truck #
rotal Number of Gate	Truck #
Observed placement of Bolts in new concrete For: (2) HDU5 holdowns at (A.1, 2-3) on page S2.01. For: (2) HDU5 = 5/8" rod, 18" embedment, 3/4" drill bit	olts Epoxy Dowels Other:
Epoxy Type: Hilti Hit-RE 500 V3 Exp. Date:2/1/23	Cleaned: YES NO
Performed on	To the following specified tensions:

Work was observed was, to the best of Brandon Burdine 's knowledge, in conformance with approved plans, specifications, and application standards of workmanship. If present, any exceptions or non-compliance conditions were brought to the attention of for corrective action, and are as follows:

See attached non-compliance report. Contractor's acknowledgment of receipt: