



# Daily Field Report

Job Address: 870 El Camino Del Mar

San Francisco, CA

Permit(s): 2018 0523 9894 S1 2021 1112 2309

Date of Inspection: 06/30/22

Fred Tenbrink reported to Guillermo with Suskind at jobsite.

## Observed placement of:

☒ Concrete ☐ Shotcrete ☐ Rebar ☐ Other: \_\_\_\_\_

For: ☐ Columns ☐ Footing ☐ Grade Beam

☐ Mat Slab ☐ Piers ☐ Piles ☐ Post Footing

☐ PT Deck ☐ Retaining Walls ☒ SOG ☐ Stairs

☐ Stem Wall ☐ Underpinning ☐ Wall

☐ Other: \_\_\_\_\_ at the following location(s):

S2.01 Garage 6.25-7, A-D

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Monitored mix #, slump, temperature, and time limit. Prepared test

☒ Cylinders ☐ Panels ☐ Other: \_\_\_\_\_

Sampled from ☒ Truck Chute ☐ Nozzle ☐ Other: \_\_\_\_\_

Strength tested at 28 days. Supplier: Allied Redy Mix

Location(s) sampled: 6.25, A

Total Number Of Sets: 1 Total Number of Samples: 5

Design	Set #1	Set #2	Set #3	Set #4
PSI	3K			
Agg. Size	*			
Slump	*			
Field				
# per set	5			
Mix#	330PB9C1			
Mix PSI	3K			
Agg. Size	Blend			
Compliant	<input checked="" type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N
Slump	4"			
Mix Temp	71			
Air Temp	58			
Total Yds	9			
Truck #	39			

Observed placement of ☐ Bolts in new concrete ☐ Epoxy Bolts ☐ Dowels ☐ Other: \_\_\_\_\_

For: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Epoxy Type: \_\_\_\_\_ Exp. Date: \_\_\_\_\_ Diameter: \_\_\_\_\_

Depth: \_\_\_\_\_ Bit size: \_\_\_\_\_ Cleaned: ☐ YES ☐ NO

Performed: ☐ Pull Test ☐ Torque Test on epoxy-set ☐ Bolts ☐ Rebar Dowels ☐ Other \_\_\_\_\_

For: \_\_\_\_\_ To the following specified tensions:

I \_\_\_\_\_

Notes: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

☒ Work was observed to the best of Tano's knowledge, in conformance with approved plans, specifications, and application standards of workmanship. If present, any exceptions or non-compliance conditions were brought to the attention of \_\_\_\_\_ for corrective action, and are as follows: \_\_\_\_\_

See attached non-compliance report. Contractor's acknowledgment of receipt: \_\_\_\_\_

NORCON, LLC. SPECIAL INSPECTION AND TESTING LABS

470 3rd Street, Suite 105 | San Francisco, CA 94107 | Phone: (415) 692-0519 | Email: info@norcon415.com