



Set # 2

Lab Compression Data Sheet

Date: 3/24/22 Inspector: Nick Taby Sample ID # 7070

Permit Number (s) 2018.05.23.9894 2021.11.12.2309

Job Address: 870 El Camino Del Mar

Job Contact: Guillermo With:

Observed the placement of: Concrete ☒ Shotcrete Rebar

Type of Structure: SOG Footing ☒ Grade beam Column
Stem Wall Retaining Wall Wall Mat Slab Post Footing
Under Pin PT Deck Piers Piles Stairs

At the following location(s) See Green area on Ref PDF

Design PSI from notes 3L Tag Mix # 330PB Mix PSI 3L Compliant ☒ N

Specified Slump: - Total yards placed 9 Nozzleman

Sampled From: Pump ☒ Nozzle Cert # Exp

Prepared The Following Samples Cylinders ☒ Panel(s) Other

	Set#	Set#	Set#	Set#	Set#	Set#	Set#	Set#
Slump:	<u>4"</u>							
Mix Temp:	<u>68°</u>							
Air Temp:	<u>50°</u>							
Agg Size	<u>Blend</u>							
Truck #:	<u>39</u>							
Location Sampled:	<u>(D, 64)</u>	<u>Orange</u>	<u>arrow</u>					

Per Set 5 Set(s) 2 Total 10 Supplier Allied

Time Batched Time Sampled Time In Truck

Test #	Age of test in days	Date	Technician	Width	Length	X- Section Area in sq."	Ultimate Load	Comp. Strength	Type of Fracture
1	3			4	8	12.56			
2	7	3/31					28659	2280	T3
3	28	4/21					71070	5650	T3
4	28	4/21					71291	5670	T2
5	28	4/21					71086	5650	T3
6	Hold								

Revised by: Date 4/21/22 28 day average 5656

☒ Work observed was, to the best of my knowledge, in conformance with the approved plans specifications and applicable standards of workmanship.

☐ With the following exceptions (See non-compliance report). Non compliance

details were brought to the attention of and signed for by: _____

Additional Notes: