



Set # 1

Lab Compression Data Sheet

Date: 3/24/22 Inspector: Nick Tobey Sample ID # 1545

Permit Number (s) 2018.05.23.9894 2021.11.12.2309

Job Address: 870 El Camino Del Mar

Job Contact: Guillermo

With: Thompson Suskind

Observed the placement of: Concrete Shotcrete X Rebar

Type of Structure: SOG Footing Grade beam Column

Stem Wall X Retaining Wall X Wall Mat Slab Post Footing

Under Pin PT Deck Piers Piles Stairs

At the following location(s) See GREEN area on Ref. PDF

Design PSI from notes 4K Tag Mix # 7001 Mix PSI 4K Compliant Y N

Specified Slump: - Total yards placed 18 Nozzleman

Sampled From: Pump Nozzle X Cert # Exp

Prepared The Following Samples Cylinders Panel(s) X Other

	Set#	Set#	Set#	Set#	Set#	Set#	Set#	Set#
Slump:	<u>2"</u>							
Mix Temp:	<u>73°</u>							
Air Temp:	<u>50°</u>							
Agg Size	<u>1/2"</u>							
Truck #:	<u>42</u>							
Location Sampled:	<u>Red arrow (F.6.1)</u>							

Per Set 5 Set(s) 2 Total 10 Supplier Allied

Time Batched Time Sampled Time In Truck

Test #	Age of test in days	Date	Technician	Width	Length	X- Section Area in sq."	Ultimate Load	Comp. Strength	Type of Fracture
1	3			3	6	7.07			
2	7	3/31					29864	4220	T3
3	28	4/21					50332	7120	T3
4	28	4/21					51880	7340	T3
5	28	4/21					50890	7190	T3
6	Hold								

Revised by: Date 4/21/22 28 day average 7216

X Work observed was, to the best of my knowledge, in conformance with the approved plans specifications and applicable standards of workmanship.

With the following exceptions (See non-compliance report). Non compliance

details were brought to the attention of and signed for by:

Additional Notes: