Work observed was to the best of Norcons knowledge in conformance with approved plans, specification and applicable standards of workmanship.

Laboratory tests results are attached if above referenced testing was performed during the time frame covered by this report.

*Limitations:* This inspection was executed in agreement with requirements; however please note that this report should not be relied upon by others, as acceptance or assurance of the inspection. The contractor is solely liable for any deficiencies or failure to follow code.

Examined by A. Mark Waldman

a Markelaldon

Date

3-14-22

Engineer

Technical Contact:

A. Mark Waldman, P.E.

CC:

Building Dept. - City of San Francisco