

## Daily Field Report

Job Address:

870 El Camino Del Mar

San Francisco, CA

Permit(s):

2018.05.23.9894 S1

Date of Inspection: 06/16/22

Brandon Burdine reported to Guerllmo with

Bolts in Epoxy Bolts in New Concrete Concrete Dowels Fireproofing Holdowns Masonry Post Tensioned Concrete Pull Test Rebar Roof Nailing Shear Walls Shotcrete Torque Test

To the following specified tensions:

at jobsite. Observed placement of: Set #1 Set #2 Design Set #3 Set #4 ✓ Concrete Shotcrete Rebar PSI 3000 Footing Columns Grade Beam Agg. Size Mat Slab Piles Post Footing Slump PT Deck Retaining Walls V SOG Stairs Field Stem Wall Underpinning # per set 5 ✓ Other: Pan Deck at the following location(s): Page S2.01 - (6.25-4, A-G) Mix# 330PB89C1 Mix PSI 3000 Agg. Size Compliant ( ) Y ( ) N Monitored mix #, slump, temperature, and time limit. Prepared test Slump 4" ✓ Cylinders Panels Other: Mix Temp 68 Sampled from ✓ Truck Chute Nozzle Other: Air Temp 59 Strength tested at 28 days. Supplier: Allied Total Yds Location(s) sampled: 3@B 36 Total Number Of Sets: 1 Total Number of Samples: 46 Truck # Observed placement of Bolts in new concrete Epoxy Bolts Epoxy Dowels For: Epoxy Type: Exp. Date: YES ( NO ( Cleaned: Performed

~	Work was observed was, to the best of	Brandon Burdine 's knowledge, in conformance with approved plans,
specifications, and application standards of workmanship. If present, any exceptions or non-compliance conditions were		
	ht to the attention of	for corrective action, and are as follows:
9	See attached non-compliance report. Contractoria calcoculadament of receipt.	

See attached non-compliance report. Contractor's acknowledgment of receipt:

on