



Liquid & Plastic Limits



MATERIAL DESCRIPTION	LL	PL	PI	%<#40	%<#200	USCS
● CLAY (see Exploratory Boring Log)	48	15	33	92.3	77.6	CL

<p>LAWRENCE B. KARP CONSULTING GEOTECHNICAL ENGINEER 100 TRES MESAS ORINDA, CALIFORNIA 94563 (925) 254-1222</p>	PLASTICITY		
	Sterbentz Residence Slope Failure Investigation 24 Saint Hill Road. Orinda		
	DATE	PROJECT	FIGURE: C
	July 2006	206036	